

# FORT LAUDERDALE FLORIDA

### CODE ENFORCEMENT BOARD HEARING AGENDA

JULY 28, 2015 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

### CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

**Note:** If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Howard Elfman, Chair • Chad Thilborger, Vice Chair • Joan Hinton

- Howard Nelson Paul Dooley Lakhi Mohnani Patrick McGee
- Joshua Miron (alternate) Robert Smith (alternate) Michael Madfis (alternate)
- **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

-----

#### HEARING SCHEDULED

\_\_\_\_\_\_

CASE NO: CE13031281

CASE ADDR: 2609 E LAS OLAS BLVD OWNER: BRANDT-ALBERT, MARIA M

MARIA M BRANDT-ALBERT REV TR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. THIS PROPERTY HAS BEEN ALTERED WITH AN ADDITION BUILT ON THE EAST SIDE OF THE HOUSE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A CARPORT/AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 3. THIS PROPERTY HAS BEEN ALTERED WITH A DOCK STRUCTURE BUILT WITHOUT A PERMIT RECORD OR INSPECTION RECORD FOR THIS BOAT DOCK.

#### FBC(2010) 105.4.1

THIS PROPERTY HAS BEEN ALTERED WITH A PATIO ROOF STRUCTURE INSTALLED ON THE N.W. CORNER OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH ELECTRICAL WORK INSTALLED ON THE DOCK AND OTHER AREAS OF UNPERMITTED (ADDITIONS) WORK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH AN AWNING INSTALLED ON THE WEST SIDE OF THE HOUSE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS AND PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

------

CASE NO: CE14040754
CASE ADDR: 91 COMPASS LA

OWNER: BRESLOW, JULIAN MARIE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 116.2.1.2.1

PART OF THE SEAWALL HAS BEEN DAMAGED AND NEEDS TO

BE REPAIRED.

\_\_\_\_\_\_

CASE NO: CE14051325 CASE ADDR: 2081 NE 56 ST

OWNER: CARLTON TERRACE CORPORATION

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

REPAIRS ARE BEING MADE TO THE BALCONY RAILINGS OF THIS TWO STORY CONDO BUILDING. THE REPAIRS ARE OVER \$1,500.00 AND WILL REQUIRE A BUILDING PERMIT.

\_\_\_\_\_\_

CASE NO: CE14070488
CASE ADDR: 888 SE 3 AVE

OWNER: COURTHOUSE LEGAL CENTER ASSN

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS COMMERCIAL PROPERTY HAS BEEN ALTERED WITH THE INTERIOR REMODELLING OF THE THIRD AND FOURTH FLOOR WITHOUT THE REQUIRED PERMITS AND/OR INSEPCTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE14110327
CASE ADDR: 433 NE 14 AVE
OWNER: BROOKS, SCOTT
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE14121289

CASE ADDR: 2900 NE 30 ST # G-9

OWNER: PRIDGEON, PAULA & STEVEN

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION THAT INCLUDES BUT IS NOT LIMITED TO THE REMOVAL AND REPLACEMENT OF THE WATER HEATER WITHOUT THE REQUIRED PERMIT AND OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY

COMPLIED AND CLOSED.

-----

CASE NO: CE14121814

CASE ADDR: 1240 BAYVIEW DR
OWNER: 1240 BAYVIEW LLC
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.4.3

THE BUILDING ON THIS PROPERTY HAS BEEN COMPLETELY DEMOLISHED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS AND/OR INSPECTIONS.

THE THE POLICE OF THE POLICE O

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15030553
CASE ADDR: 2719 NE 32 AV
OWNER: BOROWY, JAN
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE EXTERIOR DOORS WITHOUT THE

REQUIRED PERMIT AND/OR INSPECTIONS.

-----

CASE NO: CE15051064

CASE ADDR: 4300 N OCEAN BLVD
OWNER: PLAZA EAST ASSOC INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO BUILDING HAS BEEN ALTERED WITH AREAS WHERE WALLS ARE BEING OPENED UP AND PLUMBING PIPES

ARE BEING REMOVED AND REPLACED WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO BUILDING WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15051433 CASE ADDR: 1728 NE 20 AVE

OWNER: CARL A HOLCOMB REV LIV TR

HOLCOMB, CARL A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. A/C UNITS WERE INSTALLED.

2. KITCHEN CABINETS ARE BEING REPLACED WHICH

REQUIRE PLUMBING PERMIT FOR SINK INSTALLATION AND

ELECTRICAL PERMIT FOR GFI ON THE COUNTER.

#### FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SINK INSTALLATION FOR KITCHEN CABINETS.

#### FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL GFI FOR KITCHEN CABINETS AND ELECTRICAL FOR A/C UNITS.

#### FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. INSTALLATION OF DUCTLESS A/C UNITS.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

-----

CASE NO: CE15061470
CASE ADDR: 1638 RIVER LN
OWNER: COMMISSO, HELEN

HELEN G MACALPINE REV TR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR

INSPECTIONS.

#### FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

### FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING BEING DONE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE14061162
CASE ADDR: 109 NE 16 ST
OWNER: HARTMAN, JAMES D
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THE REAR PORCH OF THIS PROPERTY HAS BEEN ALTERED INTO A ROOM ENCLOSURE WITHOUT THE REOUIRED

PERMITS, INSPECTIONS OR C.O.

FBC(2010) 111.1.1

A CERTIFICATE OF OCCUPANCY IS REQUIRED FOR ALTERING THIS PORCH INTO HABITUAL LIVING SPACE.

CASE NO: CE14082064 CASE ADDR: 1009 NW 5 ST

OWNER: 1009 NW 5 STREET TR

% DUHANEY, GARY JR TRSTEE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS ON THIS FIRE DAMAGED DWELLING:

- 1. THE FIRE RECOVERY WORK WAS DONE WITHOUT PERMITS.
- 2. KITCHEN AND BATHROOM AREAS WERE REPAIRED AND UPGRADED WITH NEW PLUMBING AND ELECTRICAL FIXTURES. NEW CABINETS WERE INSTALLED.
- 3. DAMAGED DRYWALL WAS REPLACED ON THE CEILING AND WALLS.
- 4. ALL THE WINDOWS WERE REPLACED.
- 5. A DUCTED CENTRAL A/C WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15030848 CASE ADDR: 716 SW 16 ST

OWNER: DAUNTLESS PROPERTIES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND C.O:

- 1. THEY ARE ENCLOSING THE CARPORT AND EXTENDING THE EXISTING ROOF OVER THE CARPORT TO ADD A BEDROOM & BATH TO THE REAR BUILDING.
- 2. A NEW ROOF WAS BUILT ON THE ADDITION.
- 3. PLUMBING AND ELECTRICAL ALTERATIONS WERE DONE TO BUILD A BATHROOM AND BEDROOM AT THE REAR.
- 4. BUILDING A KITCHEN AREA AND ALTERATIONS TO THE EXISTING ONE.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15031138 CASE ADDR: 1520 NW 4 ST OWNER: FREEMAN, MARIA J INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. BUILDING PERMIT 05080372 FOR NEW SINGLE FAMILY RESIDENCE IS EXPIRED. THIS DWELING HAS BEEN OCCUPIED WITHOUT A FINAL INSPECTION AND C.O.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

#### FBC(2010) 111.1.1

THIS SINGLE FAMILY DWELLING WITH A CLASSIFICATION R-3, IS BEING USED WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

-----

CASE NO: CE15040555
CASE ADDR: 810 NE 4 AV
OWNER: R W L 4 INC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING WAS APPROVED TO BE USED AS A WAREHOUSE. IT HAS BEEN ALTERED AND IS BEING USED AS A NIGHT CLUB. THERE IS AN OPEN BAR AND IT IS NOW A VENUE FOR MUSIC/COMEDY SHOWS.

- 1. SEVERAL WOOD STAGES WERE BUILT AT THE REAR AND THE BAR AREA.
- 2. ELECTRICAL LIGHTS WERE HUNG OVER THE OPEN YARD AND THE USE OF ELECTRICAL EXTENSIONS CORDS SUPPLYING POWER TO THE STAGE AREA.
- 3. THERE IS A KITCHEN AREA. THEY ARE NOT APPROVED TO SELL FOOD. A PERMIT IS REQUIRED AS PER FBC 105.1.5.
- 4. THE PARKING LOT AND THE TWO EXISTING BATHROOMS ARE NOT THE STANDARD REQUIREMENT OF THE ADA OR THE FBC ACCESSIBILITY.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

#### FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP M TO AN ASSEMBLY GOUP A-2 OR A-3 WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

------

CASE NO: CE15040832 CASE ADDR: 311 SW 13 TER OWNER: CIFFONI, ANIBAL

AYALA, LUIS

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.4.11

A CENTRAL A/C UNIT WAS REPLACED WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15040944

CASE ADDR: 4004 NE 21 AV

OWNER: LENGEL, MARY ANN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS

HAVE NOT BEEN APPROVED.

- 1. BUILDING PERMIT #06022854 (BPOOLSPASF).
- 2. PLUMBING PERMIT #06070751 (PMETERIRR).
- 3. PLUMBING PERMIT #06081599 (PLAWNSPRIN).
- 4. ELECTRICAL PERMIT #06022831 (EPOOL/SPAR).

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15041065 CASE ADDR: 445 NW 11 TER

OWNER: HILL-WILLIAMS, LISA P &

WILLIAMS, STEPHEN P

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL WAS FINISHED. TODAY THEY REMAIN WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATIONS DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED TO COMPLY WITH THE FLORIDA CHILD

PROTECTION ACT FS515.

1. ELECTRICAL PERMIT #05052474 (EPOOL/SPAR).

2. BUILDING PERMIT #05052471 (BPOOL/SPAR).

3. BUILDING PERMIT #05093001 (BFENCEW SF).

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15061140

CASE ADDR: 2406 BARCELONA DR

HAJIANPOUR, MOHAMMAD A & ZOYA OWNER:

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS

WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL

SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS

HAVE NOT BEEN APPROVED.

1. BUILDING PERMIT #02060913 (INSTALL POOL).

2. ELECTRICAL PERMIT #02101609 (ELECTRIC FOR POOL).

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15061151
CASE ADDR: 309 NE 16 TER
OWNER: SIOTKAS, DOUKAS B
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS

HAVE NOT BEEN APPROVED.

1. ELECTRICAL PERMIT #02030367 (INSTALL ELECTRIC FOR POOL).

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15061152
CASE ADDR: 2006 NE 30 ST
OWNER: CLEM, RICHARD H
IRWIN, GERIANN P

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED.

- BUILDING PERMIT #02011489 (POOL/SPA/PAVER DECK).
- 2. ELECTRICAL PERMIT #02011617 (ELECTRIC FOR POOL PUMP AND LIGHTS).
- 3. PLUMBING PERMIT #02011615 (PLUMBING FOR POOL).
- 4. BUILDING PERMIT #02082063 (INSTALL WOOD FENCE WITH GATE).

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15061160
CASE ADDR: 709 NE 19 AV
OWNER: SINGER, TIMOTHY
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS

HAVE NOT BEEN APPROVED.

1. ELECTRICAL PERMIT # 02010548 (HOOK UP NEW RES

POOL).

2. BUILDING PERMIT # 02010544 (RES POOL).

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15061185 CASE ADDR: 2174 NE 55 CT

OWNER: POMERICO, JOSEPH E & BARBARA A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL WAS FINISHED. TODAY IT REMAINS WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED TO COMPLY WITH THE FLORIDA CHILD PROTECTION ACT FS515.

1. BUILDING PERMIT # 02070275 (POOL)

- 2. PLUMBING PERMIT # 02070276 (POOL PLUMBING)
- 3. ELECTRICAL PERMIT # 02070277 (ELECTRIC FOR POOL)
- 4. ELECTRICAL PERMIT # 03061391 (ELECTRIC FOR POOL HOOK UP)

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_

CASE NO: CE15030025
CASE ADDR: 2337 NW 14 ST
OWNER: BRAVOS, WILLIAM J

DAVIDSON-BRAVOS, DONNA

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. A WOOD FENCE WAS ERECTED AT THE PROPERTY LOT.

A STOP WORK WAS ISSUED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15030646

CASE ADDR: 508 NW 15 AV

OWNER: CHIWARA, GRACE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE WINDOWS ARE BEING REPLACED IN THE DWELLING

OPENINGS WITHOUT THE REQUIRED PERMIT.

A STOP WORK WAS ISSUED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15031104 CASE ADDR: 1531 NW 13 CT OWNER: RHA 2 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.4.18

CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE

REQUIRED PERMITS AND INSPECTIONS:

1. THE OLD CHAINLINK FENCE WAS REMOVED AND A NEW

WOOD FENCE WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15051316

CASE ADDR: 5200 NW 31 AVE # G-134

OWNER: CAUNITS, MARTIN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. AN ILLEGAL PENETRATION OF THE ROOF DECK AND THE FIRE RATED ATTIC SPACE BY THE OWNER OF UNIT G-134. THE OPENING WAS DONE TO INSTALL A SKYLIGHT ABOVE THE APARTMENT UNIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE15061651

CASE ADDR: 4250 GALT OCEAN DR # 2U

OWNER: SALAS, ARNOLDO JOSE ECHEGARAY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN AND BATHROOM TO INCLUDE BUT IS NOT LIMITED TO FRAMING AND DRYWALL WORK PERFORMED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN AND BATHROOM TO INCLUDE BUT IS NOT LIMITED TO PLUMBING WORK PERFORMED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN AND BATHROOM TO INCLUDE BUT IS NOT LIMITED TO ELECTRICAL WORK PERFORMED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN AND BATHROOM TO INCLUDE BUT IS NOT LIMITED TO MECHANICAL WORK PERFORMED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 110.9

THE SCOPE OF WORK PERFORMED WITHIN THIS UNIT WILL REQUIRE ARCHITECTURAL DRAWINGS TO ADDRESS ALL OF THE VIOLATIONS AND THE NEEDED CORRECTIONS FOR THESE VIOLATIONS ESPECIALLY FOR THE ELECTRICAL WORK. THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE15011051 CASE ADDR: 210 NE 3 ST

OWNER: LOS NEVADOS 3RD AVE SERIES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THERE IS A FENCE THAT HAS BEEN ERECTED ON THE

EASEMENT of THIS VACANT LOT.

CASE NO: CE15040158

CASE ADDR: 400 ISLE OF CAPRI

KUIJPER, MARTIJN PETER OWNER:

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

- 1. THE FOUR EXISTING AIR CONDITIONERS HAVE BEEN MOVED INTO THE EASEMENT WHICH IS LESS THAN TWO FEET FROM THE PROPERTY LINE.
- 2. POOL PUMPS AND CLEANING EQUIPMENT HAVE BEEN MOVED AND INSTALLED ON THE SOUTH SIDE OF HIS
- 3. A POOL AND SPA HEATER HAVE BEEN MOVED AND INSTALLED ON THE SOUTH SIDE OF HIS YARD.
- 4. A NEW GAS GENERATOR WITH NEW GAS LINES HAS BEEN INSTALLED ON THE SOUTH SIDE OF THIS YARD.
- 5. AN OUTDOOR KITCHEN HAS NOW BEEN ERECTED NEAR THE ORIGINAL LOCATION OF THE FOUR AIR CONDITIONERS. THIS CONSISTS OF THE CONSTRUCTION OF A CONCRETE OUTDOOR WALL APPROXIMATELY 12FT LONG AND 8FT TALL.
- 6. A NEW GAS LINE WAS MADE FOR THE GAS GRILL.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

RETURN HEARING (OLD BUSINESS)

------

CASE NO: CE13101030
CASE ADDR: 1329 NW 7 TER
OWNER: TOTAL HOUSING INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS, AND CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT:

- 1. AN ADDITION WAS BUILT AT THE REAR OF THE DWELLING BETWEEN 2009 AND 2010.
- 2. THIS PROPERTY WAS REROOFED WITH A PERMIT #04050956 THAT WAS LEFT TO EXPIRE.

#### FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ALTERATIONS WERE DONE TO THE ELECTRICAL SYSTEM TO BUILD THE ADDITION AT THE REAR.
- 2. THE MAIN BREAKER PANEL, METER CAN AND WEATHERHEAD WERE REMOVED AND MOVED TO A NEW LOCATION, WITH NEW CIRCUITS FOR LIGHTS AND WALL OUTLETS. BY THIS ACTION THE OWNER IS INCREASING THE AMPERAGE LOAD IN THE MAIN ELECTRICAL PANEL OVER THE TOTAL AMPS LOAD RATING THAT WAS PERMITTED.IT HAS BECOME AN ELECTRICAL FIRE HAZARD.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_

CASE NO: CE14030562 CASE ADDR: 2317 SW 34 AVE

OWNER: SUNNY BROWARD VENTURES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. THERE IS WORK IN PROGRESS WITH MAJOR RENOVATIONS INSIDE THIS PROPERTY. THIS INCLUDES THE REMOVAL AND CONSTRUCTION OF INTERIOR WALLS. THE EXISTING BATHROOMS AND KITCHEN ARE BEING ENTIRELY ALTERED WITH ELECTRICAL AND PLUMBING FIXTURES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14031442 CASE ADDR: 801 SE 18 ST

OWNER: BROOKS, DENNIS H & THO T

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. THIS MULTI-FAMILY DWELLING HAS BEEN REROOFED WITH A PERMIT THAT WAS LEFT TO EXPIRE.
- 2. THE INTERIOR HAS BEEN UPGRADED INSIDE THE KITCHEN AND BATHROOM AREAS WITH ELECTRICAL AND PLUMBING FIXTURES. THE CABINETS WERE REPLACED.
- 3. THE CENTRAL A/C UNITS FOR ALL THE RENTAL APARTMENTS WERE REPLACED.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14031887
CASE ADDR: 1140 NW 4 AVE
OWNER: VILLA, ROBERT
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT:

- 1. ONE SECTION OF THE GARAGE HAS BEEN ENCLOSED.
- 2. THE APPROVED USE HAS BEEN CHANGED TO A LIVING SPACE.
- 3. A DUCTED CENTRAL A/C WAS INSTALLED IN THE MAIN BUILDING.
- 4. THE WINDOWS WERE REPLACED AT THE REAR BUILDING (GARAGE).
- 5. ON THE FRONT OF THE MAIN BUILDINGS OPENINGS SOME WINDOWS WERE REPLACED.
- 6. AN OVERHANG ADDITION WAS BUILT AT THE REAR OF THE GARAGE TO COVER THE NEW WASHER AND DRYER AREA.

#### FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. PLUMBING ALTERATIONS WERE DONE TO BUILD A NEW KITCHEN AND BATHROOM INSIDE THE ENCLOSED SECTION OF THE GARAGE.
- 2. REAR LAUNDRY FACILITY WITH NEW WASTE PIPE, HOT AND COLD WATER SUPPLY PIPES WERE HOOKED-UP TO THE NEW PLUMBING FIXTURES.

#### FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ALTERATIONS WERE DONE TO THE ELECTRICAL SYSTEM TO BUILD THE APARMENT INSIDE THE GARAGE WITH NEW CIRCUITS FOR THE WINDOWS A/C, LIGHTS AND WALL OUTLETS, 220V POWER SUPPLY TO THE NEW KITCHEN AREA, CENTRAL A/C AND DRYER.
- 2. AT THE TIME OF MY INSPECTION, THERE WAS ELECTRICAL WORK IN PROGRESS AND BY HIS ACTIONS THE OWNER IS INCREASING THE AMPERAGE LOAD IN THE MAIN ELECTRICAL PANEL OVER THE TOTAL AMPS LOAD RATING THAT WAS PERMITTED. IT HAS BECOME AN ELECTRICAL FIRE HAZARD.

#### FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A DUCTED CENTRAL A/C SYSTEM WITH 7.5 KW ELECTRICAL HEATERS WAS INSTALLED IN THE MAIN DWELLING.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14051440

CASE ADDR: 1663 NW 15 TER

OWNER: ALLADIN, VANEL

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE DWELLING'S OPENINGS WERE BOARDED AND THE WOOD HAS BEEN REMOVED.
- 2. NEW WINDOWS AND EXTERIOR DOORS WERE INSTALLED ON THEM.
- 3. INTERIOR UPGRADE INSIDE THE KITCHEN AND BATHROOMS AREAS.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14060442
CASE ADDR: 727 NW 17 ST
OWNER: DALL 2 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND CERTIFICATE OF OCCUPANCY

FROM THE CITY BUILDING DEPARTMENT:

THIS CASE WAS OPENED TO ADDRESS THE ORIGINAL COMPLAINT CE12040793 FOR WORK WITHOUT PERMITS AND

A STOP WORK ORDER WAS ISSUED BACK THEN.

- 1. SOME MAJOR RENOVATIONS WERE DONE, OTHERS WERE IN-PROGRESS WITHOUT PERMITS. THIS INCLUDES THE REMOVAL AND CONSTRUCTION OF INTERIOR WALLS AND ALTERATIONS OF THE APPROVED FLOOR PLAN OF THE DWELLING.
- 2. THE EXISTING BATHROOMS AND KITCHEN WERE ENTIRELY ALTERED WITH ELECTRICAL AND PLUMBING FIXTURES.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14070706

CASE ADDR: 1770 NW 64 ST # 620 OWNER: CYPRESS COMMERCE LTD

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

1. THE DUCTED CENTRAL AIR HAS BEEN REPLACED BY THE TENANT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14072166
CASE ADDR: 907 NW 12 TER
OWNER: HASAN, ABEER
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOW:

- 1. THE OUTSIDE WALLS WERE RE-STUCCOED.
- 2. ELECTRICAL WIRES ARE EXPOSED IN THE METER CAN.
- 3. THE BATHROOM WINDOW AND THE EXTERIOR DOOR WERE REPLACED.
- 4. INTERIOR ALTERATIONS ARE IN PROGRESS: DRYWALL, PLUMBING AND ELECTRICAL FIXTURES HAVE BEEN REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE14072224

CASE ADDR: 3621 SW 22 ST

OWNER: MARTIN, IDANIA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. THE OWNERS OF THIS PROPERTY HAVE REMOVED A CHAIN LINK FENCE BELONGING TO 3620 SW 21 CT AND REPLACED IT WITH A WOOD FENCE.
- 2. THEY BUILT A SHED TO HOUSE LARGE DOGS AND IS ATTACHED TO THE WOODEN FENCE.
- 3. BETWEEN 2007 AND 2008 A STORAGE SHED WAS INSTALLED.
- 4. BETWEEN 2011 AND 2012 A SLAB ON GRADE WAS DONE ON THE WESTSIDE OF THE PROPERTY LOT.
- 5. IN 2012, WOOD FENCES WITH GATES WERE ERECTED ON BOTH SIDES OF THE PROPERTY FRONT FACING SOUTH.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE14080903

CASE ADDR: 320 DELAWARE AVE

OWNER: KOHUTH, RUSSELL THOMAS

%LLOYD H FALK

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

STOP WORK ISSUED.

1. THE NORTH WALLS FOOTING IS BEING REPAIRED.

2. FLOOR JOIST AND CEILING RAFTERS ARE BEING REPLACED.

- 3. THE EXISTING LIVING SPACE FLOOR LAYOUT IS BEING REDESIGNED WITH NEW FRAMING AND DRYWALL WORK.
- 4. A DUCTED CENTRAL A/C IS BEING INSTALLED.
- 5. INTERIOR ALTERATIONS OF THE ELECTRICAL AND PLUMBING SYSTEMS ARE BEING PERFORMED INSIDE THE DWELLING.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

#### FBC(2010) 115.1

ALL WORK IN PROGRESS MUST BE STOPPED UNTIL THE ENTIRE REQUIRED PERMITS ARE ISSUED.

-----

CASE NO: CE14082139
CASE ADDR: 1544 NW 9 AVE
OWNER: KDE OF FL 1 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS, AS FOLLOW:

STOP WORK ISSUED

THIS PROPERTY IS BEING UPGRADED:

- 1. WINDOWS AND DOORS ARE BEING REPLACED.
- 2. THE INTERIOR WORK OR REMODELING IS IN PROGRESS WITH NEW CABINETS INSIDE THE KITCHEN AND BATHROOM AREAS.
- 3. NEW ELECTRICAL AND PLUMBING FIXTURES ARE ALSO BEING INSTALLED.
- 4. THIS SINGLE FAMILY UNIT WAS SPLIT INTO TWO RENTAL UNITS. ALTERATIONS WERE DONE TO THE ELECTRICAL AND PLUMBING SYSTEM.
- 5. THE FLOOR PLAN WAS ALTERED TO BUILD THE SECOND UNIT WITH NEW WALLS AND THE ENCLOSURE OF HALLWAYS AND INTERIOR DOORS.

#### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

#### FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS SINGLE FAMILY DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY RESIDENCE TO MULTI-FAMILY OR DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2010) 115.1

ALL WORK IN PROGRESS MUST BE STOPPED UNTIL THE ENTIRE REQUIRED PERMITS ARE ISSUED.

-----

CASE NO: CE14101440 CASE ADDR: 2000 SW 4 AVE

OWNER: J R MANAGEMENT GROUP LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

A STOP WORK ISSUED FOR:

- 1. THE OPENING PROTECTIONS WERE REPLACED AT THE DWELLING.
- 2. THE OUTSIDE WALLS AND CEILING IN THE CARPORT AND PORCHES BELONGING TO THE PROPERTY ARE BEING STUCCO.
- 3. THE INTERIOR WALLS HAVE BEEN GUTTED AND THERE IS WORK IN PROGRESS ON THE ELECTRICAL AND PLUMBING SYSTEM TO UP-GRADE THEM.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 115.1

A STOP WORK WAS ISSUED.

CASE NO: CE14110452 CASE ADDR: 1729 NW 16 AVE

OWNER: CUKIERKORN, JACQUES

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT.

STOP WORK ISSUED

- 1. INTERIOR ALTERATIONS IN THE KITCHEN AND BATHROOM AREAS. BOTH WERE GUTTED.
- 2. FRAME AND DRYWALL WORK BEING DONE WITH NEW PLUMBING AND ELECTRICAL FIXTURES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14121618

CASE ADDR: 9 HARBORAGE ISLE DR OWNER: BALDINI, SYLVIA INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED. TODAY THEY REMAIN WORK WITHOUT PERMITS. ALSO, THEY ARE LIFE SAFETY VIOLATIONS BECAUSE THE ELCTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN

APPROVED.

1. ELECTRICAL PERMIT #11090847 Epool
2. PLUMBING PERMIT #11070846 Ppool
3. BUILDING PERMIT #11070841 Bpool
4. BUILDING PERMIT #11011633 Bpaven
5. ELECTRICAL PERMIT #11011632 Epool
6. PLUMBING PERMIT #11011631 Ppool
7. BUILDING PERMIT #11011596 Bpool

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE14121727

CASE ADDR: 650 TENNIS CLUB DR # 110

TOLSON, JOHN

TOLSON, LORI

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REOUIRED

PERMITS AND INSPECTIONS FROM THE CITY.

STOP WORK ORDER ISSUED

1. FRAMING AND NEW DRYWALL WORK WITH ELECTRICAL AND PLUMBING RESTORATIONS ARE IN PROGRESS WITH NEW FIXTURES BEING INSTALLED INSIDE THE KITCHEN AND

BATHROOMS AREAS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15011433 CASE ADDR: 1819 SE 17 ST
OWNER: THE PORT CONDO ASSN INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. A BATHROOM HAS BEEN BUILT WITHOUT PERMITS IN THE GARAGE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15040771 CASE ADDR: 201 SW 2 ST

OWNER: RIVERWALK CENTRE LTD

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS, INSPECTIONS AND C.O.

1. PLUMBING AND ELECTRICAL ALTERATIONS ARE BEING

DO TO BUILD A BAR INSIDE THE BUILDING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15040898

CASE ADDR: 5900 BAYVIEW DR
OWNER: ATALLAH, IHAB
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT PERMITS. THERE ARE ALSO LIFE SAFETY VIOLATIONS BECAUSE THE ELCTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED.

1. PLUMBING PERMIT #14010890 (PPOOL)

2. ELECTRICAL PERMIT #14010889 (EPOOL/SPAR)

3. BUILDING PERMIT #14010888 (BPOOL/SPAR)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15041034 CASE ADDR: 1404 SE 9 ST

W D INVESTMENTS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT A PERMIT. THERE ARE ALSO LIFE SAFETY VIOLATIONS BECAUSE THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN

APPROVED.

1. ELECTRICAL PERMIT #05090459 (EPOOL/SPAR) 2. BUILDING PERMIT #05090454 (BPOOL/SPAR)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15041070 CASE ADDR: 1333 NE 15 AVE SPORN, KENNETH F & OWNER: DIMARIA, MARCELLO

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT A PERMIT. THERE ARE ALSO LIFE SAFETY VIOLATIONS BECAUSE THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED

1. ELECTRICAL PERMIT #04120155 (EPOOL/SPAR) 2. BUILDING PERMIT #04120152 (BPOOL/SPAR)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13030518

CASE ADDR: 1215 SEMINOLE DR
OWNER: KEENAN, BRIAN F
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR REMODELING WITHOUT PERMITS.

.\_\_\_\_\_

CASE NO: CE13091180 CASE ADDR: 833 NW 19 AV

OWNER: BROWN, J M & SILLIE MAE EST

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. WINDOWS AND DOORS ARE BEING REPLACED.
- 2. A/C UNIT WAS REPLACED.
- 3. ELECTRICAL WORK DONE. DISCONNECTED BOX TO THE A/C
- 4. PLUMBING WORK DONE. A DRAIN LINE WAS EXPOSED ON THE NORTH SIDE OF THE HOUSE DRAINING ONTO THE GROUND.

#### FBC(2010) 105.4.4

PLUMBING INSTALLED AND EXPOSED ON NORTH SIDE OF HOUSE AND DRAINING ONTO THE GROUND WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ELECTRICAL WORK INSTALLED, DISCONNECT TO A/C WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.15

WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

------

CASE NO: CE14010952 CASE ADDR: 200 S BIRCH RD

OWNER: LEISURE BEACH ASSOCIATION INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.4.11

THIS LAUNDRY ROOM HAS BEEN ALTERED WITH THE ADDING AND/OR RELOCATION OF MECHANICAL EXHAUST DUCT WORK FOR THE DRYERS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 105.4.5

- 1. THIS LAUNDRY ROOM HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO ELECTRICAL OUTLETS AND WIRING BEING ADDED AND/OR RELOCATED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.
- 2. THIS LAUNDRY ROOM HAS BEEN ALTERED WITH LOW VOLTAGE WIRING FOR CAMERAS AND/OR OTHER DEVICES WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 110.9

THE CONDO BUILDING AND/OR ASSOCIATION WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULED AND PASS ALL REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

\_\_\_\_\_\_

CASE NO: CE14010954

CASE ADDR: 200 S BIRCH RD # 309
OWNER: WALLACE, LESTER L
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN WHICH INCLUDES BUT IS NOT LIMITED TO INTERIOR WALLS BEING ALTERED AND/OR RELOCATED, FRAMING AND DRYWALL WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN WHICH INCLUDES BUT IS NOT LIMITED TO THE PLUMBING FIXTURES BEING REMOVED AND REPLACED AND ALSO POSSIBLY RELOCATED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

#### FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN WHICH INCLUDES BUT IS NOT LIMITED TO THE ELECTRICAL BEING ALTERED OR RELOCATING SWITCHES, OUTLETS, DEVICES AND CEILING LIGHT FIXTURES WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS. THE ELECTRICAL PANEL MAY ALSO BE AN ISSUE.

#### FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

\_\_\_\_\_\_

CASE NO: CE14060058

CASE ADDR: 2500 LUCILLE DR

OWNER: KLAIRMONT, LARRY

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THERE ARE SEVERAL ITEMS THAT HAVE BEEN INSTALLED ON THIS PROPERTY WITHOUT FIRST OBTAINING THE

REQUIRED PERMITS TO INCLUDE:

A SMALL SHED.
 A GENERATOR.
 AN AWNING.
 A POOL HEATER.

CASE NO: CE14061007 CASE ADDR: 2186 NE 59 CT

OWNER: O FLAHERTY, DANIEL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH AN INTERIOR REMODEL WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF WINDOWS AND DOORS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

#### FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE14090039 CASE ADDR: 3145 NE 9 ST

OWNER: ESPOSITO ENTERPRISES INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS COMMERCIAL BUILDING HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE

REQUIRED PERMITS OR INSPECTIONS.

\_\_\_\_\_\_

CASE NO: CE14091251
CASE ADDR: 1736 SE 14 ST
OWNER: VERDUGO, CARLOS E
INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(B)

- 1. THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.
- 2. THE SEAWALL AT THIS PROPERTY IS IN NEED OF REPAIRS AND MAINTENANCE.

#### FBC(2010) 105.4.3

- 1. THIS PROPERTY HAS BEEN ALTERED WITH THE PARTIAL DEMOLITION OF A DOCK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.
- 2. THE WOODEN DOCK HAS NOT BEEN MAINTAINED AND HAS NOW DETERIORATED FROM THE ELEMENTS. THIS STRUCTURE HAS NOW BECOME A WINDSTORM HAZARD AND IS UNSAFE.

### FBC(2010) 105.4.18

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

CASE NO: CE14100227

CASE ADDR: 528 VICTORIA TER

OWNER: 528 VICTORIA TERRACE LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO THE ENCLOSURE OF THE GARAGE WITHOUT

THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO THE INSTALLATION OF WINDOWS AND

DOORS WITHOUT THE REQUIRED PERMITS AND OR

INSPECTIONS. FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL

REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED

INSPECTIONS AND PROPERLY CLOSE OUT ALL THE

REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS

CODE CASE.

-----

CASE NO: CE14110272

CASE ADDR: 1311 SEMINOLE DR OWNER: DANIELSSON, LEIF INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY IS BEING ALTERED WITH THE FOLLOWING

WORK BEING DONE WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT

LIMITED TO:

1. EXTERIOR WALL REPAIR.

2. NEW DOCK.

3. NEW TIKI HUT.

4. WHAT APPEARS TO BE POST FOR A FENCE OR TRELLIS.

5. REMOVING AND REPLACING A PAVER DECK.

\_\_\_\_\_

CASE NO: CE14110923 CASE ADDR: 1640 NE 60 ST

OWNER: SANDER, FREDERICK LEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH AN ILLEGAL STRUCTURE BEING BUILT IN THE REAR OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

\_\_\_\_\_\_

CASE NO: CE14111192

CASE ADDR: 4143 N OCEAN BLVD # 103

OWNER: HASSAN, JAMES C &

HASSAN, A L

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF ALL THE WINDOWS AND DOORS IN THE UNIT WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, AND PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE

THIS CODE CASE.

\_\_\_\_\_\_

CASE NO: CE14120559

CASE ADDR: 200 S BIRCH RD # 1111

OWNER: SHRIKI, ROY
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELING WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN

ALL REQUIRED PERMITS, PASS ALL REQUIRED

INSPECTIONS AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND

CLOSED.

\_\_\_\_\_\_

CASE NO: CE14121723
CASE ADDR: 2879 NE 28 ST
OWNER: NOLAN, GERALD N
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE SUB-DIVISION OF THE HOUSE TO CREATE SEPARATE RENTAL UNITS WITHOUT OBTAINING THE REQUIRED

PERMITS AND/OR INSPECTIONS.

## FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

## FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED BY ADDING ELECTRICAL WIRING, DEVICES AND FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE MAIN A/C UNIT WITHOUT THE REOUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT PERMITS BE OBTAINED, INSPECTED, PASSED AND CLOSED PRIOR TO COMPLYING AND CLOSING THIS CASE.

## FBC(2010) 111.1.1

THIS CODE CASE WILL REQUIRE A NEW CERTIFICATE OF OCCUPANCY IF THIS HOUSE IS SUBDIVIDED INTO SEPARATE RENTAL UNITS.

\_\_\_\_\_\_

CASE NO: CE15010524
CASE ADDR: 1000 NE 6 ST

OWNER: LAKES OF BRIDGEWATER LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF ALL THE EXTERIOR DOORS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

## FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE COMPLETE REMODELLING OF THE KITCHEN, THREE FULL BATHROOMS WHICH INCLUDES THE TILE BACKING BOARD IN THE WET AREAS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

## FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE COMPLETE RENOVATION OF THE KITCHEN AND THREE FULL BATHROOMS THAT INCLUDES THE REMOVAL AND REPLACEMENT OF ALL THE PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE COMPLETE RENOVATION OF THE KITCHEN AND THREE FULL BATHROOMS THAT INCLUDES THE REMOVAL AND REPLACEMENT OF ALL THE ELECTRICAL DEVICES WITHOUT THE REQUIRED PERMIT

AND/OR INSPECTIONS.

CASE NO: CE15011944 CASE ADDR: 609 NE 8 AV

OWNER: ELITE HOME PARTNERS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR AND EXTERIOR RENOVATIONS WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE FRONT DOOR WITHOUT THE REQUIRED

PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS BEFORE

THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15020287

CASE ADDR: 3233 NE 34 ST # 1612 CRICKETT, JOHN J OWNER: INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE STRUCTURAL WORK OF INTERIOR WALL FRAMING WITH REGULAR WHITE LUMBER (COMBUSTIBLE MATERIALS) AND DRYWALL INSTALLED WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

## FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN TWO BATHROOMS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

## FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE DEMOLITION OF ELECTRICAL, THE ILLEGAL WIRING OF ROMEX WIRING INSTALLED, ELECTRICAL BOXES INSTALLED, ELECTRICAL WIRES CUT FROM INSIDE METAL CONDUIT AND ELECTRICAL ALTERATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION OF MECHANICAL DUCT WORK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

## FBC(2010) 110.9

THE OWNER OF THIS CONDO UNIT WILL BE REQUIRED TO OBTAIN ARCHITECTURAL DRAWINGS BECAUSE OF THE SEVERITY OF THE VIOLATIONS, OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS IN ORDER TO FULLY COMPLY AND CLOSE THIS CODE CASE.

\_\_\_\_\_\_

CASE NO: CE15020352

CASE ADDR: 4010 GALT OCEAN DR # 1412

OWNER: OLSEN, DONNA M

OLSEN, JOHN C

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODEL TO INCLUDE THE KITCHEN AND TWO BATHROOMS BEING REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTION. THIS WORK WOULD HAVE INCLUDED REPLACING DRYWALL OR TILE BACKING BOARD IN THE BATHROOM WET AREAS.

## FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODEL OF THE KITCHEN AND TWO BATHROOMS WHICH INCLUDE THE REMOVAL AND REPLACEMENT OF ALL THE PLUMBING FIXTURES INCLUDING THE BATHTUB AND SHOWER PAN WITHOUT THE REPAIRED PERMITS AND/OR INSPECTIONS.

## FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODEL OF THE KITCHEN AND BATHROOMS WHICH INCLUDE THE REMOVAL AND REPLACEMENT OF ELECTRICAL SWITCHES, OUTLETS, FIXTURES AND DEVICES WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

## FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL THE REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

\_\_\_\_\_\_

CASE NO: CE15021157

CASE ADDR: 1424 NE 55 ST

OWNER: GESTION D E Q INC
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

RE-BUILDING OF A DOCK WITHOUT THE REQUIRED PERMIT

AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN THE REQUIRED PERMIT, SCHEDULE AND PASS THE REQUIRED INSPECTIONS, AND PROPERLY CLOSE OUT THE REQUIRED PERMIT TO FULLY COMPLY AND CLOSE THIS CODE CASE.

.\_\_\_\_\_

CASE NO: CE15030619
CASE ADDR: 3333 NE 33 ST
OWNER: GALT II LLC
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THE WEST SIDE OF THIS COMMERCIAL STOREFRONT SPACE HAS BEEN ALTERED WITH THE COMPLETE INTERIOR RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO STRUCTURAL WORK INCLUDING BUT NOT LIMITED TO FRAMING, DRYWALL AND CEILING GRID INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THE WEST SIDE OF THIS COMMERCIAL STOREFRONT SPACE HAS BEEN ALTERED WITH THE COMPLETE INTERIOR RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

## FBC(2010) 105.4.5

THE WEST SIDE OF THIS COMMERCIAL STOREFRONT SPACE HAS BEEN ALTERED WITH THE COMPLETE INTERIOR RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS OF:

- 1. INSTALLATION OF LOW VOLTAGE WIRING AND CAMERAS.
- 2. UPGRADED INTERIOR ELECTRICAL PANEL.
- 3. ALTERATION OF THE ELECTRICAL WIRING, ELECTRICAL BOXES AND/OR REMOVING, REPLACING OR RELOCATION OF ELECTRICAL SWITCHES, ELECTRICAL BOXES AND ELECTRICAL FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

## FBC(2010) 105.4.8

THIS COMMERCIAL BUILDING HAS BEEN ALTERED WITH THE INSTALLATION OF EXTERIOR AWNINGS ON THE SECOND FLOOR ON THE SOUTH SIDE OF THE BUILDING WITHOUT THE REQUIRED PERMIT AND OR INSPECTIONS.

## FBC(2010) 105.4.11

THE WESTSIDE OF THIS COMMERCIAL STOREFRONT SPACE HAS BEEN ALTERED WITH THE COMPLETE INTERIOR RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO THE ALTERATION OF THE MECHANICAL SYSTEM, DUCT WORK AND/OR RELATED WITHOUT THE REQUIRED PERMIT AND OR INSPECTIONS.

### FBC(2010) 105.4.15

THIS COMMERCIAL BUILDING HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF EIGHT WINDOWS ON THE SECOND FLOOR, ON THE NORTH SIDE OF THE BUILDING, WITHOUT THE REQUIRED PERMIT AND OR INSPECTIONS.

### FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO HIRE AN ARCHITECT OR ENGINEER TO PREPARE THE REQUIRED DRAWINGS, OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL OF THE REQUIRED INSPECTIONS AND PROPERLY CLOSE OUT ALL OF THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

\_\_\_\_\_\_

CASE NO: CE15040200

CASE ADDR: 4100 GALT OCEAN DR # 610 OWNER: GUTIERREZ, MARIO & SILVANA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE INTERIOR DEMOLITION AND RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH ELECTRICAL WORK BEING PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH PLUMBING WORK BEING PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH MECHANICAL WORK BEING PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

-----

CASE NO: CE15040668

CASE ADDR: 619 N FTL BEACH BLVD

OWNER: SEA CLUB OCEAN RESORT HOTEL INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A CONCRETE BLOCK WALL, WINDOWS, RAILING AND OTHER REMODELING WORK WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

\_\_\_\_\_\_

CASE NO: CE14031507 CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

### FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

### FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

------

CASE NO: CE14031823 CASE ADDR: 733 NW 15 TER

OWNER: WICKHAM, JAMES DAVID

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS, AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT:

1. A COMPLAINT WAS RECEIVED FROM PD IN REFERENCE TO A STRUCTURE ON THE REAR OF THE DWELLING THAT WAS BUILT AND IS USED AS A ROOM OR SLEEPING QUARTERS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14051264 CASE ADDR: 1324 SW 30 ST

OWNER: HOLLAND, ANDREW JAMES

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A SHED WITHOUT A PERMIT.

\_\_\_\_\_\_

CASE NO: CE14051355
CASE ADDR: 3051 NW 23 ST
OWNER: WILLIAMS, THERESA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

- 1. A SHED IN THE BACK YARD WAS ADDED TO THE HOUSE IN THE REAR BY THE POOL.
- 2. A WOOD FENCE WAS ERECTED BEHIND THE DWELLING. ALL WORK WAS PERFORMED IN 2011.
- 3. THE DWELLING WAS REROOFED WITH SHINGLES ON APRIL 19, 2006. THE ISSUED PERMIT WAS LEFT TO EXPIRE WITHOUT PASSING THE FINAL. TODAY IT REMAINS WORK WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14051438 CASE ADDR: 645 NW 14 TER

OWNER: 645 NW 14 TERRACE LANDTRUST

% SWITZER, STAN TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS, AS FOLLOWS:

1. THIS PROPERTY WAS UPGRADED. THE INTERIOR WAS REMODELED WITH NEW CABINETS INSTALLED IN THE KITCHEN AND BATHROOM AREAS.

2. NEW ELECTRICAL AND PLUMBING FIXTURES ALSO WERE INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE14062128 CASE ADDR: 2740 SW 1 ST

OWNER: BEANHEAD INVESTMENTS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THE BUILDING OPENING PROTECTIONS WERE ALTERED BY WORK PERFORMED ON THEM WITHOUT OBTAINING THE

REQUIRED PERMITS.

1. WINDOW A/C'S WERE INSTALLED AND PARTS OF THE WINDOWS WERE REMOVED AND COVERED WITH PLYWOOD TO ACCOMMODATE THE A/C UNITS.

-----

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR OWNER: WSC BRICKELL LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

## FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

------

CASE NO: CE15060586 CASE ADDR: 1709 SW 10 ST

OWNER: SILVERA, KENNETH A

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ILEGAL CONVERSION OF A SINGLE FAMILY DWELLING.
THE FLOOR PLAN HAS BEEN CHANGED BY ADDING NEW
ROOMS AND THE ELECTRICAL SYSTEM HAS BEEN ALTERED.

## FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THERE IS ELECTRICAL WIRING EXPOSED THROUGHOUT THE HOUSE AND STAPLED ALONG THE DRYWALL TO HANG LIGHTING IN THE MAKE-SHIFT ROOMS.

## FBC(2010) 111.1.1

MAKE-SHIFT ROOMS HAS BEEN ADDED TO THIS DWELLING ALTERING THE ORIGINAL USE AND MEANS OF EGRESS.

## FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

-----

------

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

\_\_\_\_\_\_

CASE NO: CE14071684
CASE ADDR: 1608 SW 10 CT
OWNER: SOFREI LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

- 1. INTERIOR ALTERATIONS OF THE ELECTRICAL, PLUMBING AND MECHANICAL SYSTEMS.
- 2. DRYWALL REPLACEMENT INSIDE THE KITCHEN AND BATHROOMS AREAS.
- 3. THE WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 4. THE PROPERTY WAS RE-ROOFED WITH SHINGLES. THE PERMIT WAS LEFT TO EXPIRE WITHOUT PASSING FINAL INSPECTIONS. TODAY IT REMAINS WORK WITHOUT PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE14111588 CASE ADDR: 814 SW 26 CT

OWNER: RANDOLPH, DONNA LE

BURNS IRREVOCABLE FAM TR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

REFERRED TO PROPERTY BY FORT LAUDERDALE POLICE. THERE ARE UNSAFE CONDITIONS INSIDE THE DWELLING.

- 1. THE ELECTRICAL PANEL WAS REMOVED FROM THE SUPPORTING WALL AND IS HANGING BY THE WIRES.
- 2. THE ELECTRICAL METER CAN HAS BEEN JUMPED WITH WIRES TO SUPPLY POWER TO THE DWELLING.
- 3. DRYWALL IS BEING REPLACED.
- 4. PLUMBING WORK IN PROGRESS INSIDE THE BATHROOMS.
- 5. A SHED THAT WAS INSTALLED WITHOUT A PERMIT. IT IS IN DISREPAIR. IT MUST BE REPAIRED OR REMOVED.

## FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

## FBC(2010) 1604.1

THE STRUCTURES FOR THE ROOF AND WALLS BELONGING TO THE REAR STORAGE SHED DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AS PER FBC 116.1.2 AND THE CONSTRUCTION IS UNDERDESIGNED, AND IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO THE WIND'S UPLIFT.

\_\_\_\_\_\_

CASE NO: CE11110991 CASE ADDR: 2845 SW 4 ST

OWNER: GALLINGTON, MARILYN K

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT.

1. NEW WINDOWS WERE INSTALLED AND THERE ARE TWO DISTINCT ADDITIONS IN THE REAR PER BCPA INSPECTOR GREG FRITZ'S E-MAIL:

WE FOUND SCREEN ENCL. REMOVED & BLOCKED UP W/CBS & WINDOWS, ADDED ANOTHER ROOM W/POWER METER INSIDE THIS NEW ROOM, CLOTHES DRYER DRAINING ON LAWN, NEW WATER HEATER, ROMEX IN LAUNDRY RM, NEW A/C UNIT NEW ELECT. TO BOTH ILLEGAL ADDITIONS, ASPHALTED A CIRCULAR DRIVE ON THE FRONT.- G.F.

## FBC(2007) 109.10

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

\_\_\_\_\_\_

CASE NO: CE15041071
CASE ADDR: 447 SW 5 AVE
OWNER: RIVER TR
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT PERMITS. THERE ARE ALSO A LIFE SAFETY VIOLATIONS BECAUSE THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN

APPROVED.

1. ELECTRICAL PERMIT #04111563 (EPOOL/SPAR)
2. BUILDING PERMIT #04111562 (BPOOL/SPAR)
3. PLIMPING PERMIT #05042727 (PROOL)

3. PLUMBING PERMIT #05042727 (PPOOL)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

------

CASE NO: CE14060539
CASE ADDR: 2496 CAT CAY LN
OWNER: 1463 PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR DEMOLITIONS AND REMODELING WORK TAKING PLACE WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

A STOP WORK ORDER WAS PLACED ON THE JOBSITE.

\_\_\_\_\_\_

CASE NO: CE14081828
CASE ADDR: 1775 NE 20 ST
OWNER: SIDDIQI, JUNAID
SIDDIQI, SAUMINI

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS, AS FOLLOWS:

STOP WORK ORDER BY JOHN CIOFFI.

1. THE WINDOWS WERE REPLACED AND INSTALLATION OF GAS SYSTEM BY DC KATZ PLUMBING.

2. THIS PROPERTY WAS UPGRADED. THE INTERIOR WAS REMODELED WITH NEW CABINETS INSTALLED IN THE KITCHEN AND BATHROOMS AREAS.

2. NEW ELECTRICAL AND PLUMBING FIXTURES WERE ALSO INSTALLED.

## FBC(2010) 105.4.4

- 1. THE OWNER HAS INSTALLED GAS LINES AT THE REAR OF THE PROPERTY.
- 2. INTERIOR ALTERATIONS OF THE KITCHEN AND BATHROOMS.

## FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

-----

CASE NO: CE14110051 CASE ADDR: 2811 NE 57 ST

OWNER: DEUTSCHE BANK NATL TR CO TRSTEE % F

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF TWO BATTER PILINGS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

## FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS FOR THIS CODE CASE TO BE FULLY COMPLIED AND CLOSED.

------